



## Damaged 1950's Westinghouse Expulsion Arrester

Externally gapped 1950 Westinghouse expulsion type arrester still on its transformer in spite of the fact that it has lost its porcelain housing. Looks like that side of the transformer is de-energized Photo taken in 2007

